





1.


M3108_02




M3108

2.


24x




6x




12x




24x



12x




72x




24x



16x




40x








6x

UF010






6x

UF020




M3108







4 12x (1479) 







5 12x (1479) 






6














11



8x 1479 

12


8x 173 




15







2.





16












22

12x 45



1.




Xmm = Xmm




90°


2.




45




45





45



2.






3.




23

12x 852



24



25



SCAN ME

