









1.




MZ103_01

rauch




2.


TYP I



TYP II 1x 1344




1344



1344

TYP III 2x 1344




1344


4x17








M4



M4x12



4x17



1

4x 244 4x17

4x 580 M4

4x 803 M4x12

TYP I

TYP II

TYP III

580

1348

803

244

2

4x 244 4x17

4x 580 M4

4x 803 M4x12

TYP I

TYP II

TYP III

580


1348

803

244

5.

TYP II



MZ103




6.

3

 $3x$

821


4x17




MZ103

7.

TYP III



2x



1344

MZ103



8.

4



6x

821


4x17





1.



2.




1344



3.




821



4.

5.



MZ103

